



WSK Auto Sales

RMB 54 Hwy 17 East
Kenora, Ontario P9N 3W8
canada

INVOICE

Invoice No.: 191905
Date: 12/06/2023
Ship Date:
Page: 1
Re: Order No.

Sold to:
NAN LEGAL SERVICES
JOE

Ship to:
NAN LEGAL SERVICES
JOE

Business No.: 868854084RT0001

Item No.	Unit	Quantity	Description	Tax	Base Price	Disc %	Unit Price	Amount
Tire Repair (2)	Each	1	2021 CHEVY TRAVERSE SER#MU154756, KMS 168455 Tire Repair - ON VEHICLE - Wheel(s) should be Retorqued After 100 KMs RIGHT FRONT	H	49.95		49.95	49.95
Subtotal:								49.95

YOUR SAFETY IS IMPORTANT TO US

Your wheels have been torqued to 140 ft/lbs

Your tire pressure has been set at
Right Front 35 PSI
Rear ~~PSI~~

WHEEL NUTS MUST BE RE-TORQUED
Failure to do so may result in a wheel separating from your vehicle and serious injury or damage.

RE-TORQUE
after 24 hours and as soon as possible within 50 kms.

Your wheels were torqued by BR

Kms on vehicle at time of wheel torque
168455 KM

NAN SERVICES CHEVY TRAVERSE VIN # MJ154756

WSK METAL RECYCLERS
17 HIGHWAY 17 EAST
KENORA ON

CARD *****4549
CARD TYPE VISA
DATE 2023/12/07
TIME 5481 17:24:18
RECEIPT NUMBER
H82014965-001-110-015-0

PURCHASE TOTAL
\$56.44

Visa Credit
A0000000031010
D07D6440F15A53A8
0000000000-

APPROVED
AUTH# 02568F 01-027
THANK YOU

NO SIGNATURE REQUIRED
CARDHOLDER COPY

IMPORTANT - RETAIN THIS COPY FOR YOUR RECORDS

Amount	56.44
Amount Paid	0.00
Owing	56.44