



399 MEMORIAL AVE, THUNDER BAY, ONTARIO P7B 3Y4
 PHONE: 807.683.4907 | FAX: 807.345.8440
 TOLL FREE: 800.465.3915 | BADANAIMOTORS.COM
 HST # 861502599 RT0001

SO # 105657

Status
 Printed 03/28/2024 4:31:15 PM

**SERVICE ORDER
 CUSTOMER COPY**

3215

User kylep Page 1

Customer No NA0229
Nishnawbe Aski Legal Services
 138 B MISSION ROAD
 FORT WILLIAM FN, ON P7J 1L2
Home (807) 629-4213 **Cell** (807) 631-7470
Bus
Email rmainville@nanlegal.on.ca
Term VISA

Advisor Amanda Burns **Promised** 03/27/2024 5:30 PM **Tag** 3215
Shop S1 **Opened** 03/27/2024 8:42 AM **Location**
Priority **Cashiered** 03/28/2024 2:39 PM **PO #**

License No CSAD576 **Odometer In** 140626 **Odometer Out** 140626 **InServ Date** 03/31/2021 **Stock No** M186
Year 2021 **Make** CHEVROLET **Model** TRAVERSE **Colour** -
Today **Vehicle ID No**
Fleet Type **1GNEVJKW4MJ144303**
Ext Warrantny

Request	Description	Job	CSR	Status		
FBC	FRONT BRAKES CAR	1	27497	Original		
Labour	Description		Hours	Amount		
FBC	FRONT BRAKES CAR		1.50	268.50		
Part	Description	Shp	SL	Bin	Price	Amount
85520396	PAD KIT	2		05C050	260.45	520.90
13546862	ROTOR	2		06B030	205.37	410.74
Rate	179.00	Parts Total		931.64		
Technician	64 -	Labour Total		268.50		
Cause	FRONT BRAKES CAR	Request Sub-total		1,200.14		
Correction	replaced front pads and rotors wheels torqued					

Request	Description	Job	CSR	Status		
RBC	REAR BRAKES CAR - PARTS ONLY	2	27497	Original		
Labour	Description		Hours	Amount		
RBC	REAR BRAKES CAR		0.00	0.00		
Part	Description	Shp	SL	Bin	Price	Amount
13516726	ROTOR	2		06A020	189.96	379.92
84794110	PAD KIT	0		RETURN	166.20	0.00
Rate	179.00	Parts Total		379.92		
Technician	14 -	Request Sub-total		379.92		
Cause	NO COMPLETE CUSTOMERPAY FOR PARTS TODAY					

Request	Description	Job	CSR	Status		
SES	SES/CHECK ENGINE LIGHT IS ON	3	27497	Original		
Labour	Description		Hours	Amount		
SES	SES/CHECK ENGINE LIGHT IS ON		1.40	250.60		
Part	Description	Shp	SL	Bin	Price	Amount
88865598	CLEANER	1		12E030	25.84	25.84
Rate	179.00	Parts Total		25.84		
Technician	15 -	Labour Total		250.60		
		Request Sub-total		276.44		

Tire Storage Terms: Any customer who has tires stored will have them stored up to a maximum of 8 months from invoice date or until customer requests to have tires removed from storage, at which point the storage term will end. Badanai Motors is not responsible for unclaimed tires at expiration of storage terms. Tires left beyond 30 days of the term expiration date will be disposed of without any liability or obligation to the customer. Signing of the repair order is deemed to be acceptance of these terms by customer.

Tire manufacturers are responsible for imposing the above tire fee. It is being used to cover the cost of meeting the tire manufactures legal responsibility to collect and recycle used tires. For information on how tires are collected and recycled please visit www.etracks.ca.

PRIVACY—PERSONAL INFORMATION IS COLLECTED IN ACCORDANCE WITH APPLICABLE PRIVACY LEGISLATION AND IS GOVERNED BY OUR DEALERSHIP'S PRIVACY POLICY. YOUR PRIVACY IS IMPORTANT TO US. ASK US IF YOU WOULD LIKE INFORMATION ABOUT OUR DEALERSHIP'S PRIVACY POLICY.

SIGNATURE: _____



399 MEMORIAL AVE, THUNDER BAY, ONTARIO P7B 3Y4
 PHONE: 807.683.4907 | FAX: 807.345.8440
 TOLL FREE: 800.465.3915 | BADANAIMOTORS.COM
 HST # 861502599 RT0001

SO # 105657

Status
 Printed 03/28/2024 4:31:16 PM

**SERVICE ORDER
 CUSTOMER COPY**

3215

User kylep Page 2

Customer No NA0229
Nishnawbe Aski Legal Services
 138 B MISSION ROAD
 FORT WILLIAM FN, ON P7J 1L2
Home (807) 629-4213 **Cell** (807) 631-7470
Bus
Email rmainville@nanlegal.on.ca
Term VISA

Advisor Amanda Burns	Promised 03/27/2024 5:30 PM	Tag 3215
Shop S1	Opened 03/27/2024 8:42 AM	Location
Priority	Cashiered 03/28/2024 2:39 PM	PO #

License No CSAD576	Odometer In 140626	Odometer Out 140626	InServ Date 03/31/2021	Stock No M186
Year 2021	Make CHEVROLET	Model TRAVERSE		Colour -
Today		Vehicle ID No	1GNEVJKW4MJ144303	
Fleet Type				
Ext Warrantny				

Cause Scan, code P0300 and P050D are set history for a cylinder #3 misfire (900 history misfires) and code U0632 is set current for no communication with the cooling fan. Diag, found the cooling fan 70A fuseblown in the battery fuse block. Jumper the cooling fan and measure the current draw at 100%, only draws 42Amps. The cooling fan may have been frozen or paced with snow when the fuse blew. Suggest we replace the fuse and have the customer retry, if the fuse blows again, the vehicle will require a new cooling fan motor. #3 ign coil will not come out without removing the intake manifold, or, I would have swapped the plug and coil with another hole to see if the misfire moves as it is not misfiring today. Suggest we add fuel conditioner to the fuel tank and see if the code returns.

Correction Add fuel conditioner to the fuel tank. R+R the 70A bar fuse for the cooling fan in the battery fuse block. Clear codes and verify cooling fan operation, ok. Customer to retry.

Labour	519.10
Parts	1,337.40
Supplies	70.00
SUB-TOTAL	1,926.50
HST	250.45
PST	(154.12)
TOTAL INVOICE	2,022.83
VISA	2,022.83

Tire Storage Terms: Any customer who has tires stored will have them stored up to a maximum of 8 months from invoice date or until customer requests to have tires removed from storage, at which point the storage term will end. Badanai Motors is not responsible for unclaimed tires at expiration of storage terms. Tires left beyond 30 days of the term expiration date will be disposed of without any liability or obligation to the customer. Signing of the repair order is deemed to be acceptance of these terms by customer.

Tire manufacturers are responsible for imposing the above tire fee. It is being used to cover the cost of meeting the tire manufactures legal responsibility to collect and recycle used tires. For information on how tires are collected and recycled please visit www.etracks.ca.

PRIVACY—PERSONAL INFORMATION IS COLLECTED IN ACCORDANCE WITH APPLICABLE PRIVACY LEGISLATION AND IS GOVERNED BY OUR DEALERSHIP'S PRIVACY POLICY. YOUR PRIVACY IS IMPORTANT TO US. ASK US IF YOU WOULD LIKE INFORMATION ABOUT OUR DEALERSHIP'S PRIVACY POLICY.

SIGNATURE: _____