

CARSTAR KENORA 1897 Hwy 17 East, RRZ 51TE 230 C-8 KENORA ON P9/13W8 PH 807-548-4031 FX 807-548-8787 HSTe765754098RT

RO #:18836 Unit #: Arrived: 8/15/2023 Ready: 8/15/2023

Estimator: Larocque, John

Customer Information	Vehicle Information	Insurance Information
Name: Nishnawbe-Aski Legal Address:	Vehicle: 2021 Chevrolet Trav Style: LT Cloth 1LT 4 DR W License:	erse Ins Co: Customer Pay a Contact:
Phone: 807-464-4052	VIN: 1GNEVGKWXMJ1547 Mileage: 143297 Mileage Out:	Phone: Claim #: Deduct: \$0.00

1 #	S# Operation	Description	Type	Price	Adj Price	Ŧ	Lbr		_	= -	
1	1 Remove/Replace	Taillamp Assembly,Otr LT	NW	\$600.37	\$677.45		2.1	Addi	Dept	Paint	Addl
2	Refinish	Cover Car Exterior									
3	Refinish	Polish LT Side scratches							R	0.5	
4		Paint Materials	PM	\$125.00					R	2.0	
5		Shop Supplies	SS	\$10.50							

Totals:	RO:	Supp:	T
Final (Combined) Totals	0.00	Supp:	Total:
Parts - New	\$600.37	\$77.08	\$677.45
PARTS TOTAL	\$600.37	\$77.08	\$677.45
Body Labor	\$231.00		\$231.00
Refinish Labor	\$275.00		\$275.00
LABOR TOTAL	\$506.00		\$506.00
Shop Supplies	\$10.50		\$10.50
Paint Materials	\$125.00		\$125,00
Sub Total	\$1,241.87	\$77.08	\$1,318.95
HST (13.000%)			\$171.46
GRAND TOTAL			\$1,490,41

CARSTAR KENORA 1897 Hwy 17 East, RR2 SITE 230 C-8 KENORA ON P9N3W8 PH 807-548-4031 FX 807-548-8787

Estimator: Larocque, John

RO #:18836 Unit #: Arrived: 8/15/2023 Ready: 8/15/2023

Vehicle Information **Customer Information** Name: Nishnawbe-Aski Legal Address:

Vehicle: 2021 Chevrolet Traverse Style: LT Cloth 1LT 4 DR Wa License: VIN: 1GNEVGKWXM154756 Mleage: 143297 Mileage Out:

Insurance Information

Ins Co: Customer Pay Contact: Phone: Claim #: Deduct: \$0.00

Thank you for bringing your vehicle to our shop for repairs. Please do not wax for at least 30 days if your vehicle has been painted. If your wheels were removed during repairs please re-torque lug nuts after 100km.

We appreciate your business.

Phone: 807-464-4052

Date Picked Up

8/15/2023 4:25:14 PM

Page # 1

8/15/2023 4:25:14 PM

